BUILDING SAFETY CERTIFICATE

No. PW2/2975046/25

It is certified that the existing building No.29/118 of HILL VALLEY SCHOOL at CHANGAMPUZHA NAGAR P.O THRIKKAKARA, COCHIN 682033 is having block(s)/Floor(s) as per details below:

Details of Block(s) in school	Block(1)
No. of Floor (s) in the Block	4

The building is owned/occupied by HILL VALLEY SCHOOL have complied with the Building safety requirements in accordance with National Building code Rules , and verified by the Assistant Engineer of Kalamassery Municipality on 10.07.2025 in the presence of Principal, Hill Valley School, Thrikkakara and that the building / premises is fit for occupancy for running school/Classes up to XII level with effect from 10.07.2025 for a period of one years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.
- 2. The additional observations if deemed necessary for the certificate may be furnished separately with the certificates.

The following documents should form part of this document;

- 1. Building fitness certificate issued by Assi. Engineer, Kalamassery Municicpality on 24.05.2025
- 2. Building Safety Certificate issued by Structural Engineer, Synergy Architects & Engineers on 04.07.2025
- 3. Fire Safety Certificate issued by The Station Officer, Fire & Rescue Station, Thrikkakara on 01.02.2025

Issued on 10.07.2025 at KALAMASSERY by

WINICIPAL OFFICE SOLUTION OF THE PARTY OF TH

Signature with Seal:

Name:

Designation:

LENIN E PEN 38429

Assistant Engineer
Kalamassery Municipality

Dated: 10.07.2025

Name & Address of Departhette :